North America's Leader in Hazardous Material Information Management

1905 Aston Avenue, Carlsbad, CA 92008 Phone (800) 451-8346 Fax (760) 602-8888

# MSDS PRODUCT INFORMATION

Date: 10/07/2005

To: MSDS Requester

From: 3E Company

Subject: The MSDS you have requested

# [ ] MSDS NOT REQUIRED

In response to your request for a Material Safety Data Sheet, according to the OSHA Hazard Communicatin Standard (Right-to-Know), the following item is an article. Articles are defined in 29 CFR 1910.1200(c). Products such as Drugs, cosmetics, food, or alcoholic beverages, wood or wood products, and tobacco or tobacco products, as defined in 29 CFR1910.1200(b)(6), are exempt from the Hazard Communication Standard. Items that are considered articles, as defined in 29 CFR 1910.1200(c), are also exempt from this Standard. Therefore, the manufacturer is not required to provide an MSDS for this product.

#### [ ] MSDS DISCONTINUED PRODUCT

In response to your request for a Material Safety Data Sheet, the manufacturer has discontinued the product listed below. The MSDS Attached is the most current version, or an MSDS is no longer available.

## [X] MSDS BEST COPY AVAILABLE

The MSDS attached is the best copy available from the manufacturer.

# [ ] MANUFACTURER NO LONGER IN BUSINESS

In response to your request for a Material Safety Data Sheet, a current MSDS could not be obtained for this product. It has been determined that the manufacturer listed below is no longer in business. A current address and phone number could not be located.

Manufacturer: Pakmix, Inc.

Product Name: Bagged Stucco Mix



#### MATERIAL SAFETY DATA SHEET

PRODUCT NAME: Bagged Stucco Mix

HMIS CODES: H FR P

PRODUCT CODE: Premixed Stucco

100B

\*\*\*\*\*\*\* SECTION 1 - MANUFACTURER IDENTIFICATION

MANUFACTURER'S NAME: PAKMIX INC.

ADDRESS.

605 INDUSTRIAL WAY

DIXON, CA 95620

EMERGENCY PHONE (707) 693-2919

DATE PRINTED:

INFORMATION PHONE: (707) 693-2919

NAME OF PREPARER:

PRESENTING SECTION II - HAZARDOUS INGREDIENTS/SARA III INFORMATION ============

REPORIABLE COMPONENTS

CAS NUMBER

VAPOR PRESSURE na Hg @ TEMP

WEIGHT PERCENT

Photo salar --- , which is promoted a superior and program. Tri Calcium Silicate

n/a n/a

TLV. 5 mg/ cubic meter (resp)rable dust)

TLV 10 mg/ cubic meter ( total dust).

\*\*\*No loxic chemical(s) subject to the reporting requirements of section 313 of Title III and of 40 CFR 312 are present. \*\*\* This MSDS is prepared to comply with the OSHA Hazard Communication Standard. (29 CFR 1910.1200) Unlisted Ingredients are not 'Hazardous per this OSHA Standard and are considered to be trade secrets of Pak nix Corporation. Identities of trade secret ingredients will be made available following the procedures specified in the standard.

BOILING RANGE: n/a VAPOR DENSITY: n/e COATING V.O.C.: 0.00 lb/gl

SPECIFIC GRAVITY (H2O=1): 2.56 **EVAPORATION RATE: n/a** 

SOLUBILITY IN WATER: Slight 0.1- 1.0 %

MATERIAL V.O.C.: 0.00 lb/gi

APPEARANCE AND ODOR: Grey powder with

send possibly rock-Odorless

# 

FLASH POINT: n/a

FLAMMABLE LIMITS IN AIR BY VOLUME-

METHOD USED: n/a

LOWER: n/a UPPER: n/a

EXTINGUISHING MEDIA= n/a

SPECIAL FIREFIGHTING PROCEDURES

n/s

UNUSUAL FIRE AND EXPLOSION HAZARDS

n/a

STABILITY: Product hardens in 6-8 hours and becomes stable.

CONDITIONS TO AVOID

None known

INCOMPATIBILITY (MATERIALS TO AVOID)

Acids, "tuotine, any additive except Water

HAZAFIDOUS DECOMPOSITION OR SYPRODUCTS

Carbor Dioxide when ailed with Acids

HAZARDOUS POLYMERIZATION™ Will not occur

# BURGES STEERSTEEN SECTION VI HEALTH HAZARD DATA AREFERENCE PRESERVED

# INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Causes initiation of mucous membrane and respiratory passages.

# SKIN AND EYE CONTACT HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Corresive to skin and eyes. Akali burns to skin and eyes may result if contacted.

# SKIN ABSORPTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Systematically toxic concentrations will probably not be absorbed through the skin.

# INGESTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Single close oral toxicity is low. No hazards anticipated from ingestion due to industrial exposure.

# HEALTH HAZARDS (ACUTE AND CHRONIC)

Acute exposure; Wet portland cament can dry the skin and cause alkali burns. Portland cament dust can tritate the skin and upper respiratory system.

Of ronic exposure; Portland cement dust can cause inflammation of the lining of the interior of the nose and inflammation of the comes, individuals who are allergic to chronium may develop an allergic dermatitis. (Portland cament may contain traces of chronium)

# CARCINGGENICITY - NTP CARCINGGEN - No | IARC MONOGRAPHS - No OSHA REGULATED - No None.

#### MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE

Persons with lung disease should avoid inhalation.

#### EMERGENCY AND FIRST AID PROCEDURES

Wash eyes immediately with water. If imitation persists, seek medical attention. For gross inhalation, remove person immediately to fresh air, give artificial respiration as needed, seek medical attention as needed.

# 

# STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Use dustless methods (vacuum) and place into container for disposal, or flush with water. Do not dry sweep and disperse particles into the air. Wear protective equipment specified below.

#### WASTE DISPOSAL METHOD

This product does not meet the definition of hazardous waste under the U.S. EPA Hazardous Waste Regulations 40 CFR 261. State or local hazardous waste regulations by apply if they are different from the federal regulations. Dispose of according to Federal, State, and Local regulations.

# PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Avoid threakage of bagged material or spilts of bulk material. Keep Dry.

#### OTHER PRECAUTIONS

None

# 

## RESPIRATORY PROTECTION

Only HIOSH-approved or MSHA-approved equipment should be used.

#### **VENTILATION**

Use sufficient local exhaust to maintain TLV's and PEL's.

#### PROTECTIVE GLOVES

Protect hands with by using rubber or leather gloves

#### EYE PROTECTION

Use protective shield (safety glasses] when exposed to dust particles.

# OTHER PROTECTIVE CLOTHING OR EQUIPMENT

Wear a promitate protective clothing. Launder contaminated clothing after use.

# MATERIAL SAFETY DATA SHEET

Page: 3

SUPER BETTE BETTE BETTE SECTION IX DISCLAIMER = PRESERVED FOR SECTION IX DISCLAIMER

The information contained herein is based on data considered accurate. However, no warranty is expressed or implied regarding the accuracy of these data or the results to be obtained from, the use thereof. Pakmix Inc. essumes no responsibility for personal injury or property damage to vendees, users or third parties caused by the material. Such vendees or users assume all risks associated with the use of the material. Customers-users of silica must comply with all applicable health and safety laws, regulations and orders.